FULLBAX SPOLKA Z O.O.
UL. SWIETY MARCIN 29/8 61-806 POZNAN

Pre-shipment Inspection Report

No.: SGF-20201030-08GZ

GENERAL INFORMATION



Product Name	Q235 metal sheets
Model number	2mm, 3mm
P/O number	lys220311
Quantity	42tons
Client name	N/A
Supplier name	N/A
Inspection date	Mar 26th , 2022
Arrival time	9:30
Departure time	12:00
Inspection location	FENGNAN
Inspector	VIVIAN
Supervisor	William

INSPECTION RESULT SUMMARY

Item		Pass/Pending/Failed	Remark
Quantity check		Pass	2mm*1500*3000 424 pieces in total 43 pieces 9 packets, 37 pieces 1 packet 3mm*1500*3000 total 114 pieces 29 tablets in 3 packs, 27 tablets in 1 pack
Products finishing ,artwork		Pass	
Product color， printing		Pass	
Product size /Weight		Pass	It cannot be weighed on site, and the factory promises that the goods are 42tons enough tons this time
TEST	functional testing	Pass	
	tensile test	N/A	
Packing carton and marks		N/A	

Inspection standard:MIL-STD-105E,Fixed, AQL 2.5/4.0

FULLBAX SPOLKA Z O.O.
UL. SWIETY MARCIN 29/8 61-806 POZNAN

Defectives list	Sample size : **80pcs**		CRITICAL	MAJOR	MINOR
		AQL	0	2.5	4.0
		AC/RE	0 / 0	5/6	7/8
		Defect found	0	0	3
About factory	**Unavailable**	Pls see the related pictures			
Inspection videos	**N/A**	**N/A**			

OVERALL CONCLUSION

passed

Comments:

Base on our inspector check in supplier's export warehouse on Mar. 16, 2022, we have below comments:

1. **All production packages are completed in warehouse.**
2. **No approved sample for comparison during inspection**
3. **It cannot be weighed on site, and the factory promises that the goods are 42tons enough tons this time.**
4. **Packing way: 2mm*1500*3000 424 pieces in total**
   43 pieces 9 packets, 37 pieces 1 packet
   3mm*1500*3000 total 114 pieces
   29 tablets in 3 packs, 27 tablets in 1 packet
5. **Inspector checked the products, finishing, outlook, size.**
   Among those 80pcs samples, we found below defects:

Defect list				
Defects	**Found quantity**	**Critical**	**Major**	**Minor**
Edge oxidation in 2mmx1500x300	**3**	**0**	**0**	**3**
Total:	**3**	**0**	**0**	**3**

6. **Base on the upon comments, so we give the final inspection result as passed**

FULLBAX SPOLKA Z O.O.
UL. SWIETY MARCIN 29/8 61-806 POZNAN

A. Quantity

Model Number	Ordered Qty	Available Qty	Packed Qty	Final Shipped Qty	Inspection Sample Qty
2mm*1500*3000	38ton / 424pcs	38ton / 424pcs	10	38ton / 424pcs	63
3mm*1500*3000	12ton / 114pcs	12ton / 114pcs	4	12ton / 114pcs	17
Total:	42ton / 538pcs	42ton / 538pcs	14	42ton / 538pcs	**80**
Comments: N/A					

A-1. Products Measurement and weight check

Item	Carton Size(cm)	Carton G.W(kg)	Product size	Product weight(kg)
2mm*1500*3000	-	-	1.99x1510x3008	-
3mm*1500*3000	-	-	2.995x1510x3002	-
Comments: The site cannot be weighed				

Products finishing ,package artwork and product colour,



Finished products storage

Finished products storage

ITEM: 2mm*1500*3000

FULLBAX SPOLKA Z O.O.
UL. SWIETY MARCIN 29/8 61-806 POZNAN

	
Product details	**Product details**
Product details	**Product details**
	

FULLBAX SPOLKA Z O.O.
UL. SWIETY MARCIN 29/8 61-806 POZNAN

Product details	Product details
	
Product details	**Product details**
Product size	**Product size**

FULLBAX SPOLKA Z O.O.
UL. SWIETY MARCIN 29/8 61-806 POZNAN

	
Product size	**Product size**
	
Product size	**Product size**
ITEM: 3mm*1500*3000	

Fullbax

FULLBAX SPOLKA Z O.O.
UL. SWIETY MARCIN 29/8 61-806 POZNAN

Product details	**Product details**
Product details	**Product details**

FULLBAX SPOLKA Z O.O.
UL. SWIETY MARCIN 29/8 61-806 POZNAN

Product details	Product details
Product details	**Product details**
Product size	**Product size**

FULLBAX SPOLKA Z O.O.
UL. SWIETY MARCIN 29/8 61-806 POZNAN

Product size	**Product size**
Product size	**Product size**

FULLBAX SPOLKA Z O.O.
UL. SWIETY MARCIN 29/8 61-806 POZNAN

Defect list				
Defects	**Found quantity**	**Critical**	**Major**	**Minor**
Edge oxidation in 2mmx1500x300	**3**	**0**	**0**	**3**
Total:	**3**	**0**	**0**	**3**
		N/A		

Note:

1. This report reflects our findings at the time and the place of inspection based on random samples selected.
2. This inspection was carried out to the best of our knowledge and abilities, and our responsibility is limited to the exercise of reasonable one.
3. This report does not relieve the sellers from their contractual obligations nor does it prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our inspection or occurring thereafter.
4. This report does not evidence shipment.

THE END OF REPORT